

扬中市深入打好污染防治攻坚战指挥部办公室文件

工作提示

市各有关单位：

1月7日，市城管局会同市攻坚办对我市相关事业单位餐饮油烟设施进行现场核查，发现部分单位餐饮油烟装置需疏通清洗（详见附件）。请各单位迅速组织落实，做好餐饮油烟装置的疏通清洗工作。相关整改情况(附整改图片)，于1月15日前报市攻坚办。

扬中市深入打好污染防治攻坚战指挥部办公室
2026年1月7日



附件

单位	人社局
照片	
	
备注	正常使用油烟净化设施，油烟净化设施排口油污重。

单位	自然资源和规划局三茅分局
照片	
	
备注	未安装油烟净化设施

单位	农业农村局
照片	
 A photograph showing a stainless steel kitchen hood with a digital display at the bottom left. The display shows the time as 10:38, the date as 2026-01-07, and the location as Yangzhou City · Huakang Medical Building. The display also includes a watermark for '今日水印 相机 真实可信' (True and Reliable) and a QR code.	 A photograph taken at the same location and time as the first one, but with more visible oil residue on the front panel of the hood. The digital display shows the time as 10:43, the date as 2026-01-07, and the location as Yangzhou City · Huakang Medical Building. The display also includes a watermark for '今日水印 相机 真实可信' (True and Reliable) and a QR code.
备注	正常使用油烟净化设施，集烟罩油污重。

单位	经济发展局
照片	
	
	
备注	集烟罩油污重，油烟净化设施和风机锈蚀严重，出口油污重。

单位	中扬置业股份有限公司（江洲西路）
照片	
备注	集烟罩油污重，三个油烟净化装置老化锈蚀，线路断裂，管道破损。